



## Profile: LUST Event

## Facility: Wapato Shell Station

Street: 631 W. 1st St.  
City ST Zip: Wapato, WA 98951  
County: Yakima  
Phone:

Latitude: +46° 26' 51.82" Dec: 46.448 °  
Longitude: 120° 25' 47.50" Dec: -120.43 °

Facility Description: Gas Station

Operator:  
Owner: Perry & Mercy Aragon  
Address (b) (6)  
Issaquah WA 98029  
Tribe: Yakama  
Tribe Owned: No

ID No: 4260116

LUST Status: Complete

Last Inspection Date: Not Visited

C&amp;E Status: No Visits

SOC Status: NA

UIC ☐AST ☐

SOC UST Status: NA

## LUST Event

Event Date: 02/22/95

Closed Date: 11/06/01

Site Manager: Mike Shepherd

Date LUST Event Reported:

Clerk: CBoullind  
Mod: 9/5/2006 12:32:52 PM

## Cleanup Milestones

Date	Status	Lead
02/22/95	Confirmed Release	RP-Lead
02/22/95	Cleanup Initiated	RP-Lead
11/06/01	Cleanup Completed	RP-Lead

## Release Information

Suspected Causes (Check all that apply)

Spill: ☐ Leaking Tank: ☐ Unknown: ☒  
Overfill: ☐ Leaking Piping: ☒  
Other: ☐

Media Affected

Surface Water: ☐ Soil: ☒  
Ground Water: ☐ Air: ☐

Depth (Feet) To Ground Water: 14

## Contractors

Work Performed:

Technico Environmental Serv Tank &amp; PCS removal, MW installed

## Contractors

Work Performed:

Shannon &amp; Wilson, Inc. MW sampling, SA

## LUST Site Visits

## Closure Funding

RP Paid: ☒Tribe: ☐LUST Trust Fund: ☐If LUST Trust Fund, over \$100,000?: ☐

## Closure Information

Clean: ☒Conditional: ☐

## How Discovered

Leak Detection: ☐Tank Closure: ☒Upgrade/Repair: ☐Spill: ☐ Operational Problems: ☐Offsite: ☐ Other: ☐Institutional Controls ☐Proprietary Controls: ☐Governmental Controls: ☐Enforcement/Permit Tools: ☐Informational Devices: ☐Engineering Systems: ☐Other Controls:



## Profile: LUST Event

**Facility: Wapato Shell Station****Facility Description:** Gas Station**ID No:** 4260116**Street:** 631 W. 1st St.**Operator:****LUST Status:** Complete**City ST Zip:** Wapato, WA 98951**Owner:** Perry & Mercy Aragon**Last Inspection Date:** Not Visited**County:** Yakima**Address:** (b) (6)**C&E Status:** No Visits**Phone:**

Issaquah WA 98029

**SOC Status:** NA**Latitude:** +46° 26' 51.82" Dec: 46.448 °**Tribe:** Yakama**UIC** ☐**AST** ☐**SOC UST Status:** NA**Longitude:** 120° 25' 47.50" Dec: -120.43 °**Tribe Owned:** No**Comments**

Source	Date	Comments
tbILUSTSite	12/29/98	Facility has requested a "no further action" ltr from EPA (11-27-96). EPA states waste oil UST at rear of former bldg needs to be addressed (still in place) and additional gw sampling be conducted to confirm non-detects (including analysis for total lead). GW elevation and gradient need to be further assessed. (NMW)
tbILUSTStatus	02/22/95	LUST Cleanup Initiated - tanks rem, pcs (453 cy) rem, mw installed
CBoulind	09/05/06	Originally managed by Geoff Keeler, transferred briefly to Wally Moon, and then finally Mike Shepherd.